

ದೊಡ್ಡಾರು ಕರಷನಹಳ್ಳ ಗ್ರಾಮ ಪಂಜಾಯಿತಿ ಕಾರ್ಯಾಲಯ

ದೊಡ್ಡೂರುಕರಪನಹಕ್ಕ, ಬಂಗಾರಜೀವೆ ತಾಲ್ಲೂಕು, ಕೋಲಾರ ಹಲ್ಲಿ,



DESCRIPTION 04-04-2024

CERTIFICATE FOR SAFE DRINKING AND SANITORY CONDITION

This is certify that an inspection by Panchayath Development Officer from Dodduru Karapanahalli Gram Panchayath inspected the Jain School, Bharath Nagar, BEML, KGF on <u>04 - 04 - 2024</u> and found that Jain School, has safe drinking water facilities for the students, staffs and members of the institutions and it is maintained by the hygienic sanction condition in the school building and the campus as per the norms prescribed by the central and state government.

Trom Kannada to English

De K Halli Gran Panchayat

Bargarfet Taluk"

PRINCIPAL JAIN SCHOOL Bharath Nagar, BEML Nagar, D.K. Halli Road, K.G.F. ಪಂಚಾಯತಿ ಆಭವೃದ್ಧಿ ಆಧನ್ಯರ ಡಿ.ಕೆ.ಹಳ್ಳಿ ಗ್ರಾಮ ಪಂಚಾಯತಿ ಬಂಗಾರಪೇಟೆ ತಾಲ್ಲೂಕು

SECRETARY
BANTIA EDUCATIONAL SOCIAL
CULTURAL AND VILLE TO THE PROPERTY OF THE

GOVERNMENT OF KARNATAKA

No: DSU/KLR/BACT/ /2024-25

District Surveillance Officer District Surveillance Unit, Kolar District, Kolar – 563 101 Date: 05/04/2024

Report of Bacteriological Analysis of Water Sample

Sample sent by Taluk: KGF Date of Collection: 02/04/2024	Opinion						
	DSU No.	Sample No.	Source & Particulars of Water Samples	M.P.N Count	S.P.P	N.S.P.P	FC
Date of Received: 02/04/2024 Date of Examination: 04/04/2024 Date of Result: 04/04/2024	57	1	RO Water, Jain School, Bharat Nagar, KGF.	00	S.P.P	411	
Note: M.P.N. Count: Most probable number of Bacteria per 100 ml of water							
D.C Text Differential Coli form Test							T
Plate Count Plate count per ml. of sample							
S.P.P : Water is satisfactory for portable purpose							
N.S.P.P.: Water is not satisfactory for Drinking purpose.							
N.S.P.P.& FC Water is not satisfactory for Drinking purpose and E. Coli							
found.					-	1	Helister

RESULT: SPP-The sample of water is suitable for portable purpose.

Microbiologist
District Surveillance Office
Kolar - 563101